

Pickings from extractions




Upper left are coils of stud threads after picking out. They don't usually come out in one piece as this might imply.

Upper right are tap remnants from picking. This is very typical when removing taps.

Lower section right and left are solid pins or dowels which were edm'd to leave a thin wall and then forced out. The center object is the core of a broken stud which someone had attempted to drill out and broke the drill. The EDM electrode is tubing and burns a donut hole as in a hole saw and this is the core that is left after the hole is edm'd. Drill is visible at bottom.

The AGB Portable EDM Model 2



For Sales and Service contact:

Email: gordon@northcoast.com

Phone: (707) 445-9111 Fax: (707) 445-0903